

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) January 1 2005 To (mo./yr.) December 31 2005
2. DOGM File Number (Mine No): M /490 /002
3. Mine Name: Smokey Joe
4. Mineral(s) Mined (or permitted to mine): Clay
5. Type of mine: ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
1/4, 1/4, 1/4, Section 9, Township 7S, Range 1W  
1/4, 1/4, 1/4, Section 8, Township 7S, Range 1W  
1/4, 1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Pabco Building Products LLC dba Interstate Brick
8. Permanent Street Address: 9780 South, 5200 West  
City, State, Zip: West Jordan, Utah 84088  
Phone: 801-280-5200 Fax: 801-280-5225
9. Company Representative (or designated operator):  
Name: John Hewitt  
Title: Assistant Plant Mgr.  
Business Address: 9780 South 5200 West  
City, State, Zip: West Jordan, UT 84088  
Phone: 801-280-5230 Fax: 801-280-5245  
☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No
2. If no - what was the last year of activity? 2004
3. If yes - how much ore or mineral was mined? none

RECEIVED

JAN 31 2006

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.  
None. John Hewitt met with Mike Ford of the BLM and discussed doing some reclamation work on the site to maintain it. See attached letter.
5. How much **additional acreage** was disturbed during the past year? none
6. How much acreage was **reclaimed** during the past year? none
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
N/a
8. What is the **total disturbed acreage of entire project** at years end? 11 acres.
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.  
The remaining additional 4,000 tons of clay at the base of the hill that was purchased in a sale contract will be hauled into the plant and a revised mine plan will be submitted prior to any more mining.

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. **The operator shall include an updated map depicting surface disturbance and reclamation performed during the year**, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**

Name (Typed or Print): John Hewitt

Title of Operator: Assistant Plant Mgr.

Signature of Operator: 






Date: 1-31-06



notes:  
 these do not exist at this mine:  
 stationary buildings  
 stationary mining processing equipment  
 utilities  
 drainage structures (berms, culverts, etc.)  
 solid or liquid waste containment areas  
 colored lines show direction and view of pictures

5

### Legend

-  overburden / rock piles
-  access road to mine from solders pass road
-  terracing and roads
-  disturbed area boundary - 10.8 acres
-  mine floor and stockpile pad area

x Prospect

x Prospect


Claypit

5616

4WD

0 25 50 100 150 200  
Meters

0 100 200 400 600 800  
Feet



Interstate Brick  
 MD49/002  
 Smokey Joe Mine

Map for MR-AR, 2005 mining activity  
 No activity took place at this location in 2005

shown on USGS Solders Pass Topo Map  
 T7S, R1W, SW1/4 Sec. 9, SLBM  
 1/06, JH